

Landslide Early Warning

නායයෑම් පිළිබඳ පෙර අනතුරු ඇඟවීම
மண்சரிவு முன்னெச்சரிக்கை

Message ID : LEWM-21-11-2023-1500-66

Update : 66 th update

Validity Period : From 15:00 hrs on 21.11.2023 To 15:00 hrs on 22.11.2023

 NBRO	<p>NATIONAL BUILDING RESEARCH ORGANISATION ජාතික ගොඩනැගිලි පර්යේෂණ සංවිධානය தேசிய கட்டிட ஆராய்ச்சி நிறுவனம் No. 99/1, Jawatta Road, Colombo 05. අංක. 99/1, ජාවත්ත පාර, කොළඹ 05. இல. 99/1, ஜாவத்தை வீதி, கொழும்பு 05.</p>
	<p>Tel./දු.ක./தொ.பே - 0112552220 Fax/ලැකිස්/தொ.ந - 0112589943</p>

<p>Warning level 1: Color Code:</p>	<p>Watch Yellow</p>	<p>Since the rainfall within the past 24 hours has exceeded 75mm, if the rain continues, be watchful on the possibility of landslides, slope failures, rock falls, cutting failures and ground subsidence.</p>
<p>අදියර 1 : වර්ණ කේතය:</p>	<p>විමසිලිමත් කහ</p>	<p>පසු ගිය පැය 24 තුළ වර්ෂාපතනය 75mm ඉක්මවා ඇති බැවින්, වර්ෂාව තවදුරටත් පවතී නම් නායයෑමේ, බෑවුම් කඩා වැටීමේ, ගල් පෙරළීමේ, පස් කණ්ඩි කඩා වැටීමේ සහ පොළොව හිරා බැසීමේ අවදානම පිළිබඳව විමසිලිමත් වන්න.</p>
<p>எச்சரிக்கை மட்டம் 1: வர்ண குறியீடு:</p>	<p>அவதானிப்பு மஞ்சள்</p>	<p>குடந்த 24 மணித்தியாலங்களில் மழைவீழ்ச்சி 75 மி.மீ களை மேலியுள்ளதனால்- மழை தொடருமாயின் மண்சரிவு, சாய்வு இடிந்து விழுகை, பாறை விழுகை, நிலவெட்டுசாய்வு இடிந்து விழுகை மற்றும் தரை உள்ளிற்றக்கம் என்பவற்றின் சாத்தியங்களுக்கான அவதானிப்புடன் இருக்கவும்.</p>
<p>Warning level 2: Color Code:</p>	<p>Alert Amber</p>	<p>Since the rainfall within the past 24 hours has exceeded 100 mm, if the rains continue, be on alert on the possibility of landslides, slope failures, rock falls, cut failures and ground subsidence, being ready to evacuate to a safe location if the need arises.</p>
<p>අදියර 2 : වර්ණ කේතය:</p>	<p>අවධාන ඇම්බර්</p>	<p>පසුගිය පැය 24 තුළ වර්ෂාපතනය 100 mm ඉක්මවා ඇති බැවින්, වර්ෂාව තවදුරටත් පවතී නම් නායයෑම්, බෑවුම් කඩා වැටීම්, ගල් පෙරළීම්, පොළොව හිරා බැසීමේ සහ පස් කණ්ඩි කඩා වැටීම් අවධානම පිළිබඳ අවධානයෙන් සිට අවශ්‍ය වුවහොත් ආරක්ෂාකාරී තැනකට යාමට සූදානම් වන්න.</p>
<p>எச்சரிக்கை மட்டம் 2: வர்ண குறியீடு:</p>	<p>எச்சரிக்கை செம்மஞ்சள்</p>	<p>குடந்த 24 மணித்தியாலங்களில் மழைவீழ்ச்சி 100 மி.மீ களை மேலியுள்ளதனால்- மழை தொடருமாயின் மண்சரிவு, சாய்வு இடிந்து-விழுகை, பாறை-விழுகை, நிலவெட்டுசாய்வு இடிந்து-விழுகை மற்றும் தரை-உள்ளிற்றக்கம் என்பவற்றின் சாத்தியங்களையிட்டு எச்சரிக்கையுடன்- தேவையேற்படின் பாதுகாப்பான இடங்களுக்கு வெளியேறும் தயார் நிலையில் இருக்கவும்.</p>
<p>Warning level 3: Color Code:</p>	<p>Evacuation Red</p>	<p>Since the rainfall within the past 24 hours has exceeded 150 mm, if the rains continue, evacuate to a safe location to avoid the risk of landslides, slope failures, rock falls, cutting failures and ground subsidence.</p>
<p>අදියර 3 : වර්ණ කේතය:</p>	<p>ඉවත්වීම රතු</p>	<p>පසුගිය පැය 24 තුළ වර්ෂාපතනය 150mm ඉක්මවා ඇති බැවින්, වර්ෂාව තවදුරටත් පවතී නම් නායයෑම්, බෑවුම් කඩා වැටීම්, ගල් පෙරළීම්, පොළොව හිරා බැසීමේ සහ පස් කණ්ඩි කඩා වැටීමේ අනතුරු වලින් වැලකීමට ආරක්ෂිත ස්ථානයකට යන්න.</p>
<p>எச்சரிக்கை மட்டம் 3: வர்ண குறியீடு:</p>	<p>வெளியேறுகை சிவப்பு</p>	<p>குடந்த 24 மணித்தியாலங்களில் மழைவீழ்ச்சி 150 மி.மீ களை மேலியுள்ளதனால்- மழை தொடருமாயின் மண்சரிவு, சாய்வு இடிந்து விழுகை, பாறை விழுகை, நிலவெட்டுசாய்வு இடிந்து விழுகை மற்றும் தரை உள்ளிற்றக்கம் என்பவற்றின் அபாயங்களை தவிர்ப்பதற்காக பாதுகாப்பான பகுதிகளுக்கு வெளியேறவும்.</p>

Locations for Potential Risk

කසයලම් අවදානම පවතින හඳුනා ගැනීමේ ප්‍රදේශ කනතියාන අපායමුள்ள ඉடங்கள்

District	Level 1 (Yellow)	Level 2 (Amber)	Level 3 (Red)
Badulla	Passara, Welimada and Haldummulla Divisional Secretariat Division(s) (DSD) and surrounding areas.	Haputhale Divisional Secretariat Division(s) (DSD) and surrounding areas.	
Hambantota	* Walasmulla Divisional Secretariat Division(s) (DSD) and surrounding areas.		
Kandy	Udunuwara, Udupalatha, Medadumbara, Gangawata Korale, Pathadumbara and Ududumbara Divisional Secretariat Division(s) (DSD) and surrounding areas.	Thumpane Divisional Secretariat Division(s) (DSD) and surrounding areas.	
Kegalle	Rambukkana and Dehiowita Divisional Secretariat Division(s) (DSD) and surrounding areas.	Yatiyanthota, ↓ Kegalle, Mawanella, Ruwanwella, ↓ Galigamuwa, ↓ Aranayaka, Warakapola and Bulathkohupitiya Divisional Secretariat Division(s) (DSD) and surrounding areas.	
Kurunegala		* Polgahawela and Rideegama Divisional Secretariat Division(s) (DSD) and surrounding areas.	
Matale	Ukuwela Divisional Secretariat Division(s) (DSD) and surrounding areas.		
Matara	Kotapola and Mulatiyana	Pasgoda Divisional Secretariat	

	Divisional Secretariat Division(s) (DSD) and surrounding areas.	Division(s) (DSD) and surrounding areas.	
Ratnapura	Kiriella, Ayagama, Pelmadulla, Kahawatta and Nivithigala Divisional Secretariat Division(s) (DSD) and surrounding areas.	Ratnapura, Openayake, Weligepola, Godakawela, Kuruwita, Kolonna, Elapatha, Balangoda, Imbulpe, Kalawana and Eheliyagoda Divisional Secretariat Division(s) (DSD) and surrounding areas.	

Note: ↑shifted one level up, ↑↑shifted two levels up, ↓shifted one level down, ↓↓shifted two levels down.
 *newly added with the last update
 Special Note: These warning levels are issued based on the cumulative rainfall received to respective areas and given weather forecast by meteorological department of Sri Lanka

Areas and places which need special attention
 All mountainous areas, manmade cut slopes and roads within the relevant DS divisions
 අදාළ ප්‍රදේශීය ලේකම් කෙට්ටිකම් තුළ පිහිටි කඳුකර බඩුම් හා ආශ්‍රිත ප්‍රදේශ තුළ පිහිටි නිර්මිත
 gpuNjr nrayf gphptpDs;shd rfy kiyg;ghq;fhd gFjpf; ; kw;Wk; ntl;l;g;gl;l epyr; rha;Tfs;;
Specially: All the landslide susceptible areas previously identified by NBRO.
විශේෂ: ජනිත ගෙඩනහිලි පර්යේෂණ සංවිධානය විසින් නැඟයුම් අවදානමක් ඇති ලෙස පුර්වයෙන් හඳුනාගත ඇති ප්‍රදේශ
 tpNrlkhf: NBROtpdhy; Kd;dh; milahsg;gLj;jg;gl;l kz;rhpTf;fhd VjepiyAs;s rfy gpuNjrq;fs;.

විශේෂ සටහන: කරුණාකර මෙම නායයෑම් පිළිබඳ පූර්ව අනතුරු හැඟවීම් කාලසීමාව තුළ පහත කරුණු වෙත ඔබේ අවධානය යොමු කරන්න.

1. පහත දැක්වෙන නායයෑම් පූර්ව ලක්ෂණ පිළිබඳ සැලකිලිමත් වන්න.
 - පොළවේ ඇති වන ඉරි නැඳීම්, ගැඹුරට හැරුණු පැළුම් හා පොළවේ ගිලා බැසීම්
 - ක්‍රමයෙන් ඇලවී යන ගස්, විදුලි කණු, වැටවල් හා දුරකථන කුළුණු ආදිය
 - ගොඩනැගිලිවල ගෙබිම හා බිත්තිමත ඇතිවන පිපුරුම් හා ඒවායේ ක්‍රමික වර්ධනය වීම්
 - එක්වර ජල උල්පත් ඇතිවීම හෝ පෙර පැවති ජල උල්පත්බොරවීම, අවහිරවීම හෝ නැතිවීම
 2. එවන් නායයෑමක පූර්ව ලක්ෂණ දක්නට ලැබෙන ප්‍රදේශ වලින් හැකි ඉක්මනින් ඉවත් වන්න.
 3. ඊට අමතරව අනතුරට භාජනය වියහැකි යැයි අනුමාන කරන ප්‍රදේශ වල ජීවත් වන පුද්ගලයින් වැඩි වශයෙන් පරීක්ෂාකාරී වියයුතු අතර දැඩි වර්ෂා තත්වය තවදුරටත් පැවතුනහොත් පුරක්ෂිත ස්ථානයක් කරා ක්ෂණිකව ඉවත්ව යාමට සූදානම්ව සිටිය යුතුය.
- සැ.යු:** ජාතික ගොඩනැගිලි පර්යේෂණ සංවිධානයෙන් සහ ආපදා කළමනාකරණ මධ්‍යස්ථානයෙන් ලැබෙන වැඩිදුර උපදෙස් අනුගමනය කරන්න.

Special Note: During this Landslide Early Warning period, please pay attention to the following:

1. Pay your attention to the following pre landslide signs,
 - Development of cracks on the ground, deepened cracks and ground subsidence
 - Slanting of trees, electrical posts, fences and telephone posts
 - Cracks in the floors and walls of buildings which are built at slopes
 - Sudden appearance of springs, emerging muddy water, blockage or disappearance of existing springs
2. People should move immediately away from the areas where they noticed the above pre-landslide signs.
3. Furthermore, people living in landslide susceptible areas should be extra vigilant and should be ready to move quickly to safe places if heavy rain continues.

Note: Communities are advised to follow the instructions given by National Building Research Organization and Disaster Management Center.

විශේෂ குறிப்பு: மண்சரிவு முன்னெச்சரிக்கை காலப்பகுதியில் பின்வருவனவற்றில் கவனம் எடுக்கவும்

1. பின்வரும் மண்சரிவு முன் அறிகுறிகளையிட்டு கவனத்தை செலுத்தவும்.
 - நிலத்தில் வெடிப்பு உருவாகுதல், ஆழமாகும் வெடிப்புகள் மற்றும் தரை உள்ளிநக்கங்கள்.
 - மரங்கள், மின் கம்பங்கள், வேலிகள், மற்றும் தொலைபேசிக் கம்பங்கள் சாய்வடைதல்.
 - சாய்வுகளில் அமைந்துள்ள கட்டிடங்களின் தரைமற்றும் சுவர்களில் வெடிப்புகள் உருவாகுதல்.
 - நிலத்திலிருந்து திடீரென நீர்நீர்நீர், சேற்று நீர் தோன்றுதல் மற்றும் தற்போதுள்ள நீர்நீர்நீர் தடைப்படுதல் அல்லது இல்லாது போகுதல்.
2. மண்சரிவுக்கு முன்னரான அறிகுறிகளை கொண்ட இடங்களிலிருந்து உடனடியாக மக்கள் அப்பால் நகர வேண்டும்.
3. மேலும், பாதிப்பு ஏதுநிலையுள்ள பகுதிகளில் வாழும் மக்கள் மேலதிக விழிப்புடன் இருக்கவேண்டும் என்பதுடன் கடும் மழை தொருமாயின் விரைவாக பாதுகாப்பான இடங்களுக்கு நகர ஆயத்தமாகவும் இருக்கவேண்டும்.

குறிப்பு: தயவுசெய்து தேசிய கட்டிட ஆராய்ச்சி நிறுவனம் மற்றும் அனர்த்த முகாமைத்துவ நிலையம் என்பவற்றின் அறிவுறுத்தல்களை பின்பற்றவும்

Previous Message ID : LEWM-20-11-2023-1700-65

Issued by:



Duty Officer

Approved by:



Director - LRRMD

21-11-2023, 15:00 hrs

Date and time issued

Landslide Research and Risk Management Division


National Building Research Organisation



Automated Landslide Early Warning Map

Landslide Early Warning Center

National Building Research Organisation, Sri Lanka



Warning Status

Message Type
Update
Message ID
LEWM-21-11-2023-1500-66
Valid Period
From: 15:00 hrs on 21.11.2023
To: 15:00 hrs on 22.11.2023
Previous Message ID
LEWM-20-11-2023-1700-65

Last Update
21-11-2023 03:05:37 PM

Legend

Warning Level 1	Watch
Color Code	
Warning Level 2	Alert
Color Code	