



වාරිමාර්ග දෙපාර්තමේන්තුව
நீர்ப்பாசனத் திணைக்களம்
IRRIGATION DEPARTMENT
(ජලවිද්‍යා හා ආපදා කළමනාකරණ අංශය)



Islandwide Water Level & Rainfall Situation in Major Rivers

DATE : 24-Nov-2023

TIME : 3:30 PM

River Basin	Tributary/River	Gauging Station					Water Level at 2:00 pm	Water Level at 3.00 pm	Remarks	Water Level Rising or Falling	6 Hr RF in mm at 3.00 pm
		Station	Unit	Alert Level	Minor Flood Level	Major Flood Level					
Kelani Ganga (RB 01)	Kelani Ganga	N' Street	ft	4.00	5.00	7.00	2.90	2.60	Normal		-
	Kelani Ganga	Hanwella	m	7.00	8.00	10.00	4.26	4.19	Normal		0.0
	Kelani Ganga	Glencourse	m	15.00	16.50	19.00	11.36	11.34	Normal		0.0
	Kelani Ganga	Kitulgala	m	3.00	4.00	6.00	1.63	2.35	Normal		0.0
	Gurugoda Oya	Holombuwa	m	3.00	3.40	5.00	1.13	1.11	Normal		0.0
	Seethawaka Ganga	Deraniyagala	m	4.80	5.80	6.40	0.83	0.83	Normal		0.0
	Kehelgamu Oya	Norwood	m	1.50	3.00	4.50	1.20	1.22	Normal		0.0
Kalu Ganga (RB 03)	Kalu Ganga	Putupaula	m	3.00	4.00	5.00	2.57	2.56	Normal		0.0
	Kalu Ganga	Ellagawa	m	10.00	10.70	12.20	8.42	8.36	Normal		0.0
	Kalu Ganga	Ratnapura	m	5.20	7.50	9.50	3.75	3.65	Normal		0.0
	Maguru Ganga	Magura	m	4.00	6.00	7.50	2.67	2.60	Normal		0.0
	Kuda Ganga	Kalawellawa (Millakanda)	m	5.00	6.50	8.00	5.98	5.96	Alert	Falling	10.1
Gin Ganga (RB 09)	Gin Ganga	Baddegama	m	3.50	4.00	5.00	3.22	3.19	Normal		0.0
	Gin Ganga	Tawalama	m	4.00	6.00	7.50	1.98	1.97	Normal		0.0
Nilwala Ganga (RB 12)	Nilwala Ganga	Thalgahagoda	m	1.40	1.70	2.80	1.71	1.71	Minor Flood		2.6
	Nilwala Ganga	Panadugama	m	5.00	6.00	7.50	5.40	5.35	Alert	Falling	0.0
	Nilwala Ganga	Pitabeddara	m	4.00	5.00	6.50	1.52	1.50	Normal		0.0
	Urubokka Ganga	Urawa	m	2.50	4.00	6.00	1.11	1.10	Normal		0.0
Walawe Ganga (RB 18)	Walawe Ganga	Moraketiya	m	3.00	5.00	7.00	3.49	3.49	Alert		0.0
Malwathu Oya (RB 90)	Malwathu Oya	Tantirimale	m	5.00	6.80	7.80	3.54	3.53	Normal		0.0
Deduru Oya (RB 99)	Deduru Oya	Moragaswewa	m	4.75	6.00	7.00	2.98	2.90	Normal		0.0
Maha Oya (RB 102)	Maha Oya	Badalgama	m	5.00	6.20	9.60	3.65	3.63	Normal		0.0
	Maha Oya	Giriulla	m	5.50	6.50	7.50	2.49	2.47	Normal		0.0
Attanagalu Oya (RB 103)	Attanagalu Oya	Dunamale	m	3.30	4.40	5.50	4.69	4.65	Minor Flood	Falling	0.0

Prepared by : G.A.S.A.Jayamal (H.A.)
Checked by : D.P.M.Alwis (H.A.)

Eng. S.P.C. Sugeeshwara
Director of Irrigation
(Hydrology & Disaster Management)
Irrigation Department
230, Bauddhaloka Mawatha,
Colombo - 07

Eng.S.P.C.Sugeeshwara
Director (Hydrology and Disaster Management)