



වාරිමාර්ග දෙපාර්තමේන්තුව
நீர்ப்பாசனத் திணைக்களம்
IRRIGATION DEPARTMENT
 (ජලවිද්‍යා හා ආපදා කළමනාකරණ අංශය)



Islandwide Water Level & Rainfall Situation in Major Rivers

DATE : 16-Dec-2023

TIME : 12:30 PM

River Basin	Tributary/River	Gauging Station					Water Level at 11:00 am	Water Level at 12:00 noon	Remarks	Water Level Rising or Falling	3 Hr RF in mm at 12.00 noon
		Station	Unit	Alert Level	Minor Flood Level	Major Flood Level					
Kelani Ganga (RB 01)	Kelani Ganga	N' Street	ft	4.00	5.00	7.00	1.20	1.25	Normal		-
	Kelani Ganga	Hanwella	m	7.00	8.00	10.00	3.29	3.22	Normal		0.0
	Kelani Ganga	Glencourse	m	15.00	16.50	19.00	10.43	10.33	Normal		0.0
	Kelani Ganga	Kitulgala	m	3.00	4.00	6.00	1.85	1.75	Normal		0.0
	Gurugoda Oya	Holombuwa	m	3.00	3.40	5.00	0.80	0.80	Normal		0.0
	Seethawaka Ganga	Deraniyagala	m	4.80	5.80	6.40	0.88	0.85	Normal		0.3
	Kehegamu Oya	Norwood	m	1.50	3.00	4.50	0.90	0.91	Normal		0.0
Kalu Ganga (RB 03)	Kalu Ganga	Putupaula	m	3.00	4.00	5.00	2.52	2.47	Normal		0.0
	Kalu Ganga	Ellagawa	m	10.00	10.70	12.20	7.28	7.24	Normal		0.0
	Kalu Ganga	Ratnapura	m	5.20	7.50	9.50	3.01	2.97	Normal		0.0
	Maguru Ganga	Magura	m	4.00	6.00	7.50	2.66	2.69	Normal		0.0
	Kuda Ganga	Kalawellawa (Millakanda)	m	5.00	6.50	8.00	6.62	6.59	Minor Flood	Falling	0.0
Gin Ganga (RB 09)	Gin Ganga	Baddegama	m	3.50	4.00	5.00	4.15	4.16	Minor Flood	Rising	1.0
	Gin Ganga	Tawalama	m	4.00	6.00	7.50	3.08	3.07	Normal		0.0
Nilwala Ganga (RB 12)	Nilwala Ganga	Thalgahagoda	m	1.40	1.70	2.80	1.93	1.93	Minor Flood		0.0
	Nilwala Ganga	Panadugama	m	5.00	6.00	7.50	5.87	5.88	Alert	Rising	0.0
	Nilwala Ganga	Pitabeddara	m	4.00	5.00	6.50	2.69	2.63	Normal		0.0
	Urubokka Ganga	Urawa	m	2.50	4.00	6.00	1.89	1.78	Normal		0.0
Walawe Ganga (RB 18)	Walawe Ganga	Moraketiya	m	3.00	5.00	7.00	2.50	2.48	Normal		0.0
Yan Oya (RB 67)	Yan Oya	Horowpatana	m	6.00	7.50	10.50	5.74	5.93	Normal		3.8
Malwathu Oya (RB 90)	Malwathu Oya	Tantirimale	m	5.00	6.80	7.80	5.56	5.64	Alert	Rising	3.4
Maha Oya (RB 102)	Maha Oya	Badalgama	m	5.00	6.20	9.60	2.82	2.81	Normal		0.0
	Maha Oya	Giriulla	m	5.50	6.50	7.50	1.56	1.56	Normal		0.0
Attanagalu Oya (RB 103)	Attanagalu Oya	Dunamale	m	3.30	4.40	5.50	2.84	2.78	Normal		0.0

Prepared by : A.A.M.Arawindi (H.A.)
 Checked by : K.K.C.U.Dilshan (H.A.)

Eng. S.P.C. Sugeeshwara
 Director of Irrigation
 (Hydrology & Disaster Management)
 Irrigation Department
 230, Bauddhaloka Mawatha,
 Colombo - 07

Eng.S.P.C.Sugeeshwara
 Director (Hydrology and Disaster Management)