



වාරිමාර්ග දෙපාර්තමේන්තුව
 நீர்ப்பாசனத் திணைக்களம்
IRRIGATION DEPARTMENT
 (ජලවිද්‍යා හා ආපදා කළමනාකරණ අංශය)



Islandwide Water Level & Rainfall Situation in Major Rivers

DATE : 19-Dec-2023

TIME : 6:30 PM

River Basin	Tributary/River	Gauging Station					Water Level at 5:00 pm	Water Level at 6:00 pm	Remarks	Water Level Rising or Falling	9 Hr RF in mm at 6.00 pm
		Station	Unit	Alert Level	Minor Flood Level	Major Flood Level					
Kelani Ganga (RB 01)	Kelani Ganga	N' Street	ft	4.00	5.00	7.00	2.00	2.10	Normal		-
	Kelani Ganga	Hanwella	m	7.00	8.00	10.00	3.44	3.38	Normal		0.0
	Kelani Ganga	Glencourse	m	15.00	16.50	19.00	10.93	10.90	Normal		0.0
	Kelani Ganga	Kitulgala	m	3.00	4.00	6.00	2.02	1.89	Normal		0.0
	Gurugoda Oya	Holombuwa	m	3.00	3.40	5.00	1.14	1.14	Normal		0.0
	Seethawaka Ganga	Deraniyagala	m	4.80	5.80	6.40	0.81	0.81	Normal		0.0
	Kehelgamu Oya	Norwood	m	1.50	3.00	4.50	1.05	1.05	Normal		0.0
Kalu Ganga (RB 03)	Kalu Ganga	Putupaula	m	3.00	4.00	5.00	1.82	1.90	Normal		4.7
	Kalu Ganga	Ellagawa	m	10.00	10.70	12.20	8.00	8.03	Normal		26.3
	Kalu Ganga	Ratnapura	m	5.20	7.50	9.50	3.34	3.26	Normal		1.4
	Maguru Ganga	Magura	m	4.00	6.00	7.50	2.65	2.71	Normal		2.7
	Kuda Ganga	Kalawellawa (Millakanda)	m	5.00	6.50	8.00	5.38	5.42	Alert	Rising	45.8
Gin Ganga (RB 09)	Gin Ganga	Baddegama	m	3.50	4.00	5.00	3.82	3.80	Alert	Falling	26.6
	Gin Ganga	Tawalama	m	4.00	6.00	7.50	3.01	3.12	Normal		25.9
Nilwala Ganga (RB 12)	Nilwala Ganga	Thalgahagoda	m	1.40	1.70	2.80	1.96	1.96	Minor Flood		4.0
	Nilwala Ganga	Panadugama	m	5.00	6.00	7.50	6.20	6.18	Minor Flood	Falling	2.3
	Nilwala Ganga	Pitabeddara	m	4.00	5.00	6.50	1.81	1.89	Normal		1.8
	Urubokka Ganga	Urawa	m	2.50	4.00	6.00	1.10	1.09	Normal		0.0
Walawe Ganga (RB 18)	Walawe Ganga	Moraketiya	m	3.00	5.00	7.00	3.52	3.51	Alert	Falling	0.0
Yan Oya (RB 67)	Yan Oya	Horowpatana	m	6.00	7.50	10.50	6.03	5.98	Normal		7.7
Malwathu Oya (RB 90)	Malwathu Oya	Tantirimale	m	5.00	6.80	7.80	7.03	7.00	Minor Flood	Falling	0.6
Maha Oya (RB 102)	Maha Oya	Badalgama	m	5.00	6.20	9.60	3.70	3.63	Normal		2.0
	Maha Oya	Giriulla	m	5.50	6.50	7.50	2.54	2.45	Normal		0.0
Attanagalu Oya (RB 103)	Attanagalu Oya	Dunamale	m	3.30	4.40	5.50	4.64	4.60	Minor Flood	Falling	0.0

Prepared by : K.K.C.U.Dilshan (H.A)
 Checked by : K.G.D.C.Dissanayaka (H.A.)

Eng. S.P.C. Sugeeshwara
 Director of Irrigation
 (Hydrology & Disaster Management)
 Irrigation Department
 230, Bauddhaloka Mawatha,
 Colombo - 07

Eng.S.P.C.Sugeeshwara
 Director (Hydrology and Disaster Management)